I EAD SAFE"

INSTALLATION COMPLETION REPORT

Subir

Pella Mid-Atlantic, Inc. 12100 Baltimore Avenue, Suite 1 Beltsville, MD 20705 301-957-7070 MHIC136537 VA 2705170176

Windows and Doors

Williams and Boole		
Customer Name: Address: Phone Day: Night: Cell: Customer Name: Address: Customer Name: Address: Customer Name: Customer	Installation Date: Order#: Crew: Delivery: Install Pick-up: stom Stain or Paint:	10/1 - 10/2/21 710OSH0U7 Leon 7 - 9 AM
C.O.D. Payment Schedule: Delivery Payment (due before installation): Completion Payment: If paying by check – text picture & customer name to pay	ments@pellamidatlantic.com	m
Finance: Pl Customer Complete the following after walk through with crew leader. List Any Deficiencies:		
Item# Spe	ecific Problem	
55 WONG SIZC NEW SIZ		1/2
0 0 0000		1
60 wrong Size new siz	ze 31/4 × 66	
R	- 11	
15,35 and 45 all three windows h	ave a gas pr	oblem
Customer Comments: Customer Signature: Crew Leader Signatur	Date:	10-02-21

Renovation Recordkeeping Checklist

Name of Firm: Pella Ma	a day tie no.
Date and Location of Renovation Job Name:	6)(b) (6)(b) (6)(b) (6)
Order Number: 7008	HNUT
Brief Description of Renovation: Pemale	So I was down 1200
Name of Assigned Renovator:	(6) (6) install new windows
Name(s) of Trained Worker(s), if used:	
Name of Dust-Sampling Technician, Inspector or R	lisk Assessor, if used:
	n qualifications (training certificates, certifications) on file
Certified renovator provided training to workers of	on (check all the second)
Posting warning signs	The state of the s
Maintaining containment	Setting up plastic containment barriers Avoiding the spread of dust to adjacent areas
Waste handling	Post-renovation cleaning
Copy of the "Test Kit Documentation Form" provide	-
	to the property owner/occupant
Warning signs posted at entrance to work area	
Work area contained to prevent spread of dust and	d debris:
All objects in the work area removed or covered (interiors)	Doors in and within 20 feet of the work area closed and sealed (exteriors)
HVAC ducts in the work area closed and covered (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust
Windows in the work area closed (interiors)	Floors in the work area covered with taped-down plastic (interiors)
Windows in and within 20 feet of the work area closed (exteriors)	Ground covered by plastic extending 10 feet from the work area; plastic anchored to building and weighed down by heavy objects (exteriors)
Doors in the work area closed and sealed (interiors)	If necessary, vertical containment installed to prevent migration of dust and debris to adjacent property (exteriors)
Waste contained on-site and while being transporte	
Work site properly cleaned after renovation:	
	eting misted, folded dirty side inward, and taped for removal
Work area surfaces and objects cleaned using	HEPA vacuum and/or wet cloths or mops (interiors)
Certified renovator performed post recovery	control wet cloths or mops (interiors)
Cloths used.	ing verification (describe results, including the number of wet and dry cloths used):
If dust clearance testing was performed instead	, attach a copy of report.
Certify under penalty of law that the above information	
(b) (6)	10-02-3 (
	Date



VIEWED TO BE THE BEST.*

Date_10-02-2

		No. of Concession, Name of Street, or other Desires, Name of Street, Original Street, Origi					
/	(b)	(6)	,	Sign -In Time	ain	Sign-out Time	24
						1	
			*				

United States Environmental Protection Agency This is to certify that



repair, and painting activities pursuant

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires May 18, 2020

NAT-26214-2

Certification #

January 28, 2015

Issued On



Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch

LEAD

INSTALLATION COMPLETION REPORT

Subir
Pella Mid-Atlantic, Inc.
12100 Baltimore Avenue, Suite 1
Beltsville, MD 20705
301-957-7070
MHIC136537

MHIC136537 VA 2705170176

Windows and Doors

				4017
Customer Name:		Installation D		12/7
Address:		Order		710OSH0U7
		Cre	7	Simon/Tim
Phone Day:		Deliver	·	
Night:		Install Pick-u	p:	7-10am
Cell:		Custom Stain or Pair	nt:	
If paying by card (Visa, Master Ca	ck – text picture & customer name to I – call into (301) 957-7008 ard, Discover & American Express) pelow to authorize that financing		tlantic.com	
Customer				
Complete the following List Any Deficiencies: Item#	g after walk through with crew lea	Specific Problem		
	 			
-	-			
	-			
Customer Comments.	DONE)			
·				
				1 1-
Customer Signature:			Date:	12/7/2021
Sacromer eignature.				
Crew Leader Signatur			Date: _	12/7/21



Name of Firm: Pella Mid-	ATLANTIC INC.			
Date and Location of	(6)(b) (6)(b) (6)(b) (6)			
Job Name:) (5)(8) (5)(8) (6)			
Order Number: 7100 SHOU7				
Brief Description of Renovation: TNSTa	lle 2 luindous.			
Name of Assigned Renovator:	(6)(b)(6)(b)(6)(b)(6)			
Name(s) of Trained Worker(s), if used:	(a) (a)(b) (a)(b) (d)			
Name of Dust-Sampling Technician, Inspector or Ri	,			
Copies of renovator and dust-sampling technician	qualifications (training certificates, certifications) on file			
Certified renovator provided training to workers o	n (check all that apply):			
Posting warning signs	✓ Setting up plastic containment barriers			
Maintaining containment	Avoiding the spread of dust to adjacent areas			
(X) Waste handling	Post-renovation cleaning			
Copy of the "Test Kit Documentation Form" provide	led to the property owner/occupant			
Warning signs posted at entrance to work area				
X Work area contained to prevent spread of dust and	d debris:			
All objects in the work area removed or covered (interiors)	Doors in and within 20 feet of the work area closed and sealed (exteriors)			
HVAC ducts in the work area closed and covered (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust			
Windows in the work area closed (interiors)	Floors in the work area covered with taped-down plastic (interiors)			
Windows in and within 20 feet of the work area closed (exteriors)	Ground covered by plastic extending 10 feet from the work area; plastic anchored to building and weighed down by heavy objects (exteriors)			
Doors in the work area closed and sealed (interiors)	If necessary, vertical containment installed to prevent migration of dust and debris to adjacent property (exteriors)			
Waste contained on-site and while being transporte				
Work site properly cleaned after renovation:				
	eting misted folded dirty side investoral			
All chips and debris picked up; protective sheeting misted, folded dirty side inward, and taped for removal Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interiors)				
Certified renovator performed post-renovation cleaning verification (describe results including the number of				
used plastic and vacuum. all time and Eleaning all				
If dust clearance testing				
I certify under penalty o				
	(2/2/20			
Name and Title	Date			





Date 12/-2

			1			
		51	Sign in T		T	
			Sign -in Time		Sign and a	- 1
			18:18 A	M.	Sign-out Time	. 1
	l-		10:	1	12110 PM	
		_			1.1	
			1		,	
				-	-	
					1	
		7	The state of the s			
		1			- 4	- 1
		-		-		
						-
			-			
		1		T		
	-	-				
				-		\neg
						\dashv
- 1		-				1
- 1		-		-		7
L				-		-
- 1						1
		1	7			1
-		-		+		1
1				1		1
						1
		1		T		
1		+-		+		-
-		1		1		
1						
		1				
-				1		
		·				
				-		

United States Environmental Protection Agency This is to certify that



Estate Construction

has fulfilled the requirements of the conduction of the conduction

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires May 18, 2020

NAT-26214-2

Certification #

January 28, 2015

Issued On



Mahle Fr

Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch

--- IN THE IN THE

CREW:	A A	
CUSTOMER NAME:		
INSTALL DATE:		
DOCUMENT CREW RECORDKEEPING SIGN-IN SHEET LSI PHOTOS	Missing	RECEIVED